Date:

Monday, 07/07/2008 8:15:44 AM

User:

Linda Lacelle

Process Sheet

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Estimate Number

: 40322 : 10346

P.O. Number

This Issue

Previous Run

: 07/07/2008

Prsht Rev. : NC First Issue

: //

: 40321

S.O. No. :

Type : SKIDTUBES

Drawing Name

Part Number

: D2596 : D2596 REV D

Drawing Number Project Number

: N/A : D

Drawing Revision

Due Date

Material

: 14/07/2008

: 205 SKIDTUBE "I" BEAM

Qty:

10 Um:

Each

Written By

Checked & Approved By

Comment

: Est: D 99.02.02

Changed QA to QC, Added Step 6 and Cost D

Est Rev:E 07-07-09 Incorperated DEO 9183 JLM

Additional Product

Job Number:



Seq. #:

1.0

Machine Or Operation:

Description:

D25003100

Ext'n -`I' Beam Web 4"

1.0000 Each(s)/Unit Total:

10.0000 Each(s)

Extrusion "I" Beam Web 4"

Pick;

Comment: Qty.:

Part Number D2500-3-100

Description

Extrusion


2.0

SKIDTUBES 1

SKIDTUBESS RESOURCE 1







2- Use Jig DT8093 to drill pilot holes #30

3- Open to 0.630" diameter as per Dwg D2596

4- Deburr

SL 8-7-9



3.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1 Acid Etch and Alodine per QSI 005 4.1



4.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

(jõ



Dart Aerospace Ltd

	. copace zia							
W/O:			WORK ORDER	CHANGES				
DATE	STEP	PR	OCEDURE CHANGE	8	y Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							:	
			•					
Part No:		PAR #:	Fault Category:	NCR: `	Yes No DO	QA:	Date:	
				C	A: N/C Clos	ed:	Date:	
NOD.			WORK ORDER NON-COM	JEORMANCE (I	ICR)			

	WORK ORDER NON-CONFORMANCE (NCR)									
	Description of NC	Corrective Action Section B			\/i5i4i	_				
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector			
							i			
	STEP	STEP Description of NC Section A	STEP Section A Initial	STEP Section A Initial Action Description	STEP Section A Initial Chief Eng Chief Eng Chief Eng Sign & Date	STEP Section A Initial Chief Eng Chief Eng Sign & Date Verification Section C	STEP Section A Section A Section C S			

NOTE: Date & initial all entries

Date:

Monday, 07/07/2008 8:15:44 AM

User:

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: 205 SKIDTUBE "I" BEAM

Job Number: 40322

Part Number: D2596

Job Number:



Seq. #:

Machine Or Operation:

Description:

5.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock Location: LG

6.0

QC21

FINAL INSPECTION/W/O RELEASE





MF 08-07-10

Comment: FINAL INSPECTION/W/O RELEASE

Job Completion




Dart Ae	rospace Li	id .							
W /O:			WORK ORDER	CHANGES				****	
DATE	STEP	PRO	CEDURE CHANGE	E	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						!************************************			
Part No:		PAR #:	Fault Category:	NCR:	Yes N	o DQ	A:	Date:	
				C	QA: N/C	Close	d:	_ Date: _	
NCR:		V	VORK ORDER NON-CON	IFORMANCE (NCR)				
DATE	STEP	Description of NC	Corrective Actio		· · · · · · · ·	Verifi	cation	Approval	Approval

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC		Corrective Action Section B			Approval			
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Chief Eng	Approval QC Inspecto		
						(1		

NOTE: Date & initial all entries

DELEASEN



DETAIL SCALE 1:4 1.750 3.500 1.750 0.50 Ø0.63 REFER TO DETAIL A 0.50 (REF) (22 PLACES) - 1.750 Mo Hosp REFER TO 8.75 DETAIL A 17.38 32.75 (REF) EQUAL SPACES 8.19 PITCH 26.00 34.19 42.38 /D\ 46.01 50.56 /D/ 85.59 91.50

D2596 WEB

댊

Copyright © 1996 by DART AEROSPACE LTD

DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

-) MATERIAL:
- MAKE FROM D2500-3-100 EXTRUSION
- 2) FINISH:
- CHEMICAL CONVERSION COAT PER DART QSI 005 4.1

99.50

- 3) ALL DIMENSIONS ARE IN INCHES
- 4) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
-) DEBURR SHARP EDGES 0.010 TO 0.020

Dart Ae	rospace Ltd							
W/O:			WORK ORDER	CHANGES	- · · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PR	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No:		PAR #:	Fault Category:	NCR: Ye	s No DQ	A:	Date:	
				QA	: N/C Close	d:	Date: _	
NCR:		,	WORK ORDER NON-CON	IFORMANCE (NO	CR)			
			Corrective Actio	n Section P	· · · · · · · · · · · · · · · · · · ·	-		

	WORK ORDER NON-CONFORMANCE (NCR)								
	Description of NC		Corrective Action Section B				T		
STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	Approval QC Inspector		
			,						
			*						
			,						
				·					
			·		and the state of t				
	STEP	STED Description of NC	STEP Description of NC Section A Initial	STEP Description of NC Section A Initial Chief Eng Corrective Action Section B Action Description Chief Eng	STEP Description of NC Section A Chief Eng Chi	STEP Description of NC Section A Initial Chief Eng Chi	STEP Description of NC Section A Chief Eng Chi		

NOTE: Date & initial all entries